Certificate of Testing

Issued By:

CULP FABRIC CENTER

2742-A Tucker Street Extension Burlington, NC 27215

(336) 229-2562

The following listed pattern is in compliance with TB 117-2013 regulations. Under TB 117-2013 the fabric must meet all three of the following requirements to be considered a "Pass"- 1. The vertical char cannot exceed 45 mm or $< 1 \, \frac{3}{4}$ ", 2. The test specimens cannot smolder more than 45 minutes and 3. The test specimen cannot transition into an open flame.

Actual Results:

Kedar	Pass
Pary Jone	Date: 7/8/2014
Quality Assurance Manager	
Culp, Inc.	

Pattern: